

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	57090	((force stress strain load) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 13:33
L2	15897	((force stress strain load pull\$4 push\$5 compress\$5 press\$5 tensi\$5) near3 (top convertible)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 14:24
L3	3	((force stress strain load pull\$4 push\$5 compress\$5 press\$5 tensi\$5) near3 (convertible)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 13:10
L4	1	1 and ((force stress strain load pull\$4 push\$5 compress\$5 press\$5 tensi\$5) near3 (convertible)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 13:10
L5	0	((force stress strain load pull\$4 push\$5 compress\$5 press\$5 tensi\$5) near3 (top near2 convertible))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 13:12
L6	81	((force stress strain load pull\$4 push\$5 compress\$5 press\$5 tensi\$5) near3 (top near2 convertible))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 13:24
L7	2	1 and 6	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 13:12
L8	4	6 and ((force stress strain load) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 14:24
L9	416	(top near2 convertible).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 13:24
L10	3	9 and ((force stress strain load) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 14:13
L11	6	("6,273,492") or ("6,299,233") or ("4,749,193")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/27 14:30

L12	32	9 and ((position proximity distance travel) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 14:12
L13	7	12 and ((force stress strain load)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 14:13
L14	0	(convertible near2 top) near5 ((force stress strain load) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 14:25
L15	0	(convertible near2 top) same ((force stress strain load) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 14:26
L16	5	(convertible near2 top) same ((force stress strain load) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/27 14:26
L17	2	("6456027").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/27 14:39
L18	2	("6273492").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/27 14:40
L19	42	pulldown near3 actuat\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/27 14:41
L20	0	19 and 9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/27 14:41

L21	4	19 and convertible	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/09/27 14:41
-----	---	--------------------	---	----	----	------------------